Construction Memorandums

	CONSTRUCTION MEMORIAL	
Dota	2003	Number
Date	Description Description	Number
08/27	Preconstruction Notification Concern	03-13
08/25	Guardrail Components -Timber Block (SAT)	03-12
08/25	New Specification Dealing with Demolition (DAK)	03-11
07/22	Summary of Changes of HMA Contracts for Construction in 2003 (GGP)	03-10
07/15	Use of Circular Traffic Vehicle Detection Loops (GGP)	03-09
05/19	Salvaging of Raised Pavement Markers (GGP)	03-08
05/15	Operations Conference Follow-Up (DAK)	03-07
05/06	PG Binder Sampling and Testing (GGP)	03-06
05/05	Acceptance of Widening Mixture (GGP)	03-05
04/30	Specifications 801.10 & 801.12 (4)	03-04
04/30	Non-Standard pavement Joints (PCCP) (SAT)	03-03
01/29	Buy American Specifications (DAK)	03-02
01/21	Certification for Category 1 and 2 Temporary Traffic Control Devices	03-01
	2002	 N
Date	Description (CAT)	Number
10/07	Section 801 Changes Regarding Measurement / Payment (SAT)	02-12
07/10	Test Procedure Exception for HMATheoretical Maximum Specific Gravity	02-11
07/00	and Density of Bituminous Paving Mixtures (AASHTO T 209)	00.40
07/02	Contractor's Acceptance Procedures on HMA Volumetric and SMA Contracts	02-10
07/01	ET-2000 Manufacturer Recommended Installation Changes	02-09
06/21	Revised Change Order Approval Policy (DAK)	02-08
06/13	Frequency Manual Amendment -Pre-Formed Joint Filler for Concrete(TDB)	02-07
06/12	Recyclable Spent Foundry Sand (DAK)-(Revised 09/10/02)	02-06
05/29	2002 SMA Specifications (TDB)	02-05
05/10	Recycled Concrete (DAK)	02-04
04/19	HMA Binder Content Testing Policy	02-03
04/10	Field Density of Soil, Soil-Aggregate, & Aggregate (SAT)	02-02
01/24	Specification Changes Involving "Basis for Use" for Temp. Traffic Control	02-01
	Devices(DAK)	
Data	2001	Nicopologia
Date	Description Clarification of Field Office Specification 105 17 (DAK)	Number
10/17	Clarification of Field Office Specification 105.17 (DAK)	01-13
10/16	Expansion Joint Installation (SAT)	01-12
10/04	Use of Fly Ash in Concrete after Oct 15 (TDB)	01-11
07/24	Curing-Sealing Materials (TDB)	01-10
07/24	Timber/Wood Blocks used as Guardrail Components (TDB)	01-09
07/11	Maintenance of Attenuator & Guardrail End Treatments (DAK)	01-08 01-07
06/25	Bridge Paint Specification Changes (GGP) Accordance of Quality Control Plans for Pridge Planning (CCP)	
06/12 05/30	Acceptance of Quality Control Plans for Bridge Planning (GGP)	01-06 01-05
05/30	HMA Binder Content Testing Policy (TDB) Microsilica Pridge Dock Overlays (TDB)	01-05
04/17	Microsilica Bridge Deck Overlays (TDB) Clarification of Specification 105.17 (Field Office) (DAK)	01-04
04/05		01-03
02/27	Guardrail End Treatments Special Provisions (DAK) Donsity and Moisture Controls on HMA Mixtures (PLV)	01-02
01/02	Density and Moisture Controls on HMA Mixtures (RLY)	01-01
Data	2000 Description	Number
Date	Description Maintenance of Traffic Plans (TDP)	Number
12/14	Maintenance of Traffic Plans (TDB)	00-20
12/14	Time Extensions (TDB)	00-19

10/18	Worksite Traffic Supervisor (TDB)	00-18
09/21	Use of Fly Ash in Concrete after October 15 (TDB)	00-17
09/05	Spec Revision for 909.02(e) (TDB)	00-16
07/07	QC/QA HMA Mixture Appeals (RLY)	00-15
06/23	Temporary Pavement Markings, 801.10(a)2 (RLY)	00-14
06/20	Change Order and Time Extension Approval Authority (RLY)	00-13
06/09	Construction of Concrete Public Road Crossovers (DAK)	00-12
05/24	Bridge Painting Subcontractors (TDB)	00-11
03/31	HMA Notched Wedge Longitudinal Joint (RLY)	00-10
03/31	Plate Samples, HMA Thickness Greater Than 75 mm (RLY)	00-09
03/31	HMA Roller (RLY)	80-00
03/20	Random Crack Remediation for Concrete Pavement (PCCP) (DAK)	00-07
03/10	Conclusion of report on Embankment Widening (TDB)	00-06
03/06	Spec 904.02(d) Surface Aggregate Requirements (TDB)	00-05
03/06	Spec for Glass Beads and Thermoplastic (TDB)	00-04
03/01	HMA Binder Content Policy 2000 (RLY)	00-03
02/04	Guidelines for Transportation Enhancement Projects (TDB)	00-02
01/05	Tracking Purchase Order Amounts (RLY)	00-01
	1999	
Date	Description	Number
10/27	Making and Curing "Opening to Traffic" Beams (DAK)	99-15
10/19	Use of Foundry Sand in 1999 (GGP)	99-14
09/24	Bridge Painting in the Field (GGP)	99-13
09/15	Fast Dry Traffic Paint (RLY)	99-12
09/01	Revised 801, Effective September 1, 1999 (RLY)	99-11
08/31	Field Office computers - Y2K (RLY)	99-10
08/12	Ignition Oven for HMA Mixture with Dolomite (RLY)	99-09
07/23	Random Transverse Midpanel Cracking of PCCP (TDB)	99-08
05/03	TD 459, QA Quantity Adjustments (RLY)	99-07
04/23		,, 0,
04/23	Use of Maturity Meter for PCC Pavement (TDB)	99-06
04/23	Use of Maturity Meter for PCC Pavement (TDB) Revised Details to Standard Drawings for Guardrail Transition, Type	
04/23	Use of Maturity Meter for PCC Pavement (TDB) Revised Details to Standard Drawings for Guardrail Transition, Type TGB99-03 (DAK)	99-06 99-05
	Use of Maturity Meter for PCC Pavement (TDB) Revised Details to Standard Drawings for Guardrail Transition, Type TGB99-03 (DAK) Longitudinal Joints in HMA (RLY) Detail Changes to Standard Drawings for Guardrail Transition, Type TGB	99-06
04/23 04/09 03/30	Use of Maturity Meter for PCC Pavement (TDB) Revised Details to Standard Drawings for Guardrail Transition, Type TGB99-03 (DAK) Longitudinal Joints in HMA (RLY) Detail Changes to Standard Drawings for Guardrail Transition, Type TGB (DAK)	99-06 99-05 99-04 99-03
04/23	Use of Maturity Meter for PCC Pavement (TDB) Revised Details to Standard Drawings for Guardrail Transition, Type TGB99-03 (DAK) Longitudinal Joints in HMA (RLY) Detail Changes to Standard Drawings for Guardrail Transition, Type TGB	99-06 99-05 99-04